

Studebaker SERVICE BULLETIN

*Index for 1954 Bulletin
Bulletins 284 through 296
Jan Dec*

FEBRUARY

NO. 296A



1955

SERVICE BULLETIN INDEX - No. 284, January, 1954 through 296, December, 1954

This Service Bulletin Index lists all the articles published in Studebaker Service Bulletins during the year 1954, from service Bulletin No. 284, January through No. 296, December.

The articles are cross-referenced by subject matter, to make location easier.

REFERENCE	BL. NO.	PAGE	MODEL	REFERENCE	BUL. NO.	PAGE	MODEL
- A -				B - Cont'd.			
ACID RESISTANT ENAMEL FOR BATTERY CARRIERS	289	5		BRAKE - forward shoe and lining kit	288	2	1953 Comm & Land Cruiser
AERO GRAY ENAMEL	287			lining	284		15G, 5H
AIR CLEANER (WET TYPE)	294	3	1953-1954 Comm	parking handle, cable bleeder wrench	284	3	4H, 14G, C&K
ALBERTA BLUE ENAMEL	287	3			285	4	
AMAZON GREEN ENAMEL	287	4		- C -			
AMERICAN BOSCH SERVICE	284	8		CADET GRAY ENAMEL	287	4	
ANTIFREEZE	287	5		CARBURETOR - air cleaner	294	3	1953-1954 Comm
ANTIFREEZE	294	2		Carter changes	284	2	15G
ANTIFREEZE	295	5		051" main metering	288	7	15G, 5H
ANTIRATTLER IN FRONT DOORS	288	6	14G, 15G, 4H, 5H Sedan & Station Wagon	'jet VB models 6-112 and 6-113	288	3	V8
ASH RECEIVER - REAR SEAT	289	2	Station Wagon	gaskets	289	4	3R28 & 3R38
ASSEMBLY OF RING GEAR TO CARRIER 4.10 CHAMPION REAR AXLE	290	5	12G, 14G, 15G	high altitude rods and jets	294	3	16G6, 16G8
AURA BLUE ENAMEL	287	5		porous fuel bowl, Stromberg replacement	291	2	V8
AUTOMATIC DRIVE	294	4	1955 Comm	Stromberg throttle valve blades, Stromberg	291	1	V8
failure to move forward after reverse operation	290	3		Stromberg	'84	5	1954 Comm
gasket kit	285	1	15G	CARTER CARBURETORS	291	2	V8
multiple disc clutch friction discs	292	2	15G	CASCADE GREEN ENAMEL	284	2	15G
selector linkage adjustment	289	1	15G, 5H with AD & PS	CHADRON RED ENAMEL	294	4	
erratic multiple disc clutch action in U-joint flange	290	2		CHAMPION H-12 SPARK PLUG	287	4	
upshift, mx. kick-down speeds	294	3	AD	CLAIMS - forms and tags not allowed on propeller shafts with under coating overspray return parts	286	1	V8
AUTOMOTIVE DIAGNOSIS	295	1	16G8, 6H	CLIMATIZER - air duct maximum heat	285	3	
AZORE GREEN ENAMEL	294	2		CLIP - rear seat	'89	4	
	287	4			'86	6	
- B -				CLIMATIZER - air duct maximum heat	'86	1	1954 Sedan
BODY - conversion, rear seat center arm rest door and mouldings	284	7	1953 C & K	CLIP - rear seat	286	7	
front floor mats and carpets	287	1	1953-1954	CLUTCH PEDAL SPRING	287	1	Station Wagon
leak at top of door	287	5	1954 Pass. Cars	CONNECTING ROD ALIGNER TOOL	290	4	1951-1954
	285	3	Station wagon	CONVERSION, REAR SEAT CENTER ARM REST	284	4	
				COOLING - fan shroud interference	284	7	1953 C & K
				poster	285	2	1953-1954 C & K
				CRANKSHAFT - rear bearing oil seal	288	3	
				rear bearing oil seal	'86	6	1954 V8's
					288	3	V8

REFERENCE	BUL NO.	PAGE	MODEL	REFERENCE	BUL. NO.	PAGE	MODEL
- D -				F - Cont'd.			
DEFROSTER - rear window	287	5	Reoal Land Cruiser	FORWARD BRAKE SHOE AND LINING KIT	288	2	1953 Comm & Land Cruiser
DISTRIBUTOR ROTOR	290	5	1954 Comm, 3R28, 3R38	FOUR-SPEED SYNCHROMESH TRANSMISSION ASSEMBLY (T98)	292	3	3R Series
DOOR AND BODY MULDINGS	287	1	1953-1954	FRAME ASSEMBLIES	288	3	15G 5H
Dow Corning No. 4	291	4		FRONT DOORS - antirattler in	288	6	14G, 15G, 4H, 5H Sedan & Station Wagon
front, lock deflector	295	2		lock deflector	295	2	
glass breakage	290	6	1953 & 1954	FRONT FLOOR MATS AND CARPETS	287	5	1954 Pass. Cars
trim panels	286	8	1953-1954		289	4	15F, 5H
DOW CORNING No. 4	291	4		FUEL PUMP FILTER	285	2	V8
DUTCH BRAND PROTECTIVE PADS	295	8		- G -			
- E -				GASOLINE TANK FILLER COMPARTMENT filler housing	291	2	
ELECTRICAL - Champion				filler hose interference	289	2	1953-1954 Pass. Cars
H12 spark plug	286	1	V8	filler interference	291	3	14G, 15G, 4H, 5H Except Station Wagon
spark plug gasket	292			GEARSHIFT LINKAGE	785	3	14G, 15G, 4H, 5H
spark plug (J7)	285	3		linkage adjustment	286	3	14G, 15G, 4H, 5H
ELKO GRAY ENAMEL	287	4		GOLD METALLIC ENAMEL	294	4	
ENCINO CREAM ENAMEL	294	4		GOVERNOR VALVE SPRINGS	295	1	1954-1955 AD
ENGINE - crankshaft rear bearing oil seal	286	6	1954 V8's	- H -			
crankshaft rear bearing oil seal	288	3	V8	HANDLE ON SLIDING WINDOW GLASS	784	1	15GD, 5HD
installing rear cap screws on oil pan	288	8	"Comm 6"	HEADLINING - installation	292	1	
loss of oil pressure	286	4	4H, 5H (C&K)	HEAVY-DUTY SHOCKABSORBERS	291		
oil leak, rear	290	2	4H 5H, 3R28, 3R38	HIGH ALTITUDE RODS AND JETS	794	3	16G6, 16G8
noise	287	5	5H	- I -			
oil leak, timing gear cover	290	4	1954 Champ. 3R5, 10, 15	INSTALLING REAR CAPSCREWS ON OIL PAN	188		"Comm 6"
perfect circle piston rings	288	1	A11	INSTANT SOLDERING GUN	292	3	
tappet wrench	287		V8	- J -			
valve setting plate	284	3	3H	J-589-D - REAR AXLE PINION SETTING TOOL	284	4	
valve spring cover	285	1	G - 15G	J-4655 - REAR SPRING BUSHING REMOVER AND REPLACER	286	9	Station wagon
valve tappet adjustment	292	2	V8	J-4704 - GEAR PUSHER	286	9	
vibration damper flywheel	292	3	V8	J-5664 - PITMAN ARM PULLER	289	5	Champ. & 1951054 Comm
ERRATIC MULTIPLE DISC CLUTCH ACTION IN AUTOMATIC TRANSMISSION	290	2		- K -			
EYEBROW SEALER	285	2	15G 5H	JOHNSON ARMATURE LATHE	289	5	
- F -				"KEY TO METAL BUMPING"			
FAILURE TO MOVE FORWARD AFTER REVERSE OPERATION AUTOMATIC DRIVE TRANSMISSION	290	3			287	7	
FAN SHROUD INTERFERENCE	285	2	1953-1954 C & K				
1.051" MAIN METERING JET V8 CARBURETOR MODELS 6-112 and 6-113	288	3	V8				
Z-SPEED SYNCHROMESH TRANSMISSION	296						
FLOOR - front mats and carpets	287	5	1954 Pass. Cars				
mats and carpets - front	289	4	15G, 5H				
FOG LAMP KITS	289	2	1954 Sedan & Land Cruiser				
30 amp fuse	284	1	15G, 5H				

REFERENCE	BL. NO.	AGE	MODEL	REFERENCE	IBUL. NO.	PAGE	MODEL
- L -				P - Cont'd.			
LANCE GREEN ENAMEL LEAK AT TOP OF DOOR	287	3		PITMAN ARM PULLER-J-5664	289	5	Champ. & 1951-54 Comm
cargo compartment	285	3	Station Wagon				
cargo compartment	287	6	Station Wagon	POROUS FUEL BOWL - Stromberg (V8) carburetors	291	2	V8
LOSS OF OIL PRESSURE	292	3	Station Wagon	PORTO-POWER POWER STEERING, COVER GASKET	284	8	
	286	4	4H, 5H (C & K)	POWER TAKE-OFF Spicer	291	4	14G, 15G, 4H, 5H
- M -							3R16, 17, 28, 38, & T98 Synchronesh Trans.
MALIBU BROWN ENAMEL MATS AND CARPETS - front floor	287	4		PROTO TORQUE WRENCH	288	8	
	287	5	1954 Pass. Cars		284	8	
MAUVE TAN ENAMEL	287	5		- R -			
MAXIMUM CLIMATIZER HEAT	286	7		RADIATOR - fan shroud interference	295	2	1953-1954 C & K
MIST BLUE METALLIC ENAMEL	294	4					
MIST GREIGE METALLIC ENAMEL	294	4		RADIO, INSTRUMENT PANEL	284	4	15G, 5H
MISTURE IN TRUNK LID	286	8	1953-1954	REAR ARM REST - Conversion, center	284	7	1953 C&K
MULTIPLE DISC CLUTCH FRICTION DISCS	292	2	15G	REAR AXLE - assembly of ring gear to carrier	290	5	12G, 14G, 15G
"MULTI-VIS" AND COMBINED SERVICE RATINGS EXPLAINED	290	1		4.10 champion pinion setting tool - J-589-D	284	4	
- N -							
1955 MODELS	293			ratio	290	4	5HD/OD
NOCTURNE BLUE ENAMEL	287	4		ratio change	288	6	15G, 5H
NYLON UPHOLSTERYWATERSPOTS	295	2		speedometer and charts	284	5	1954 Pass. Cars
- O -							
.051" MAIN METERING JET V8 Carburetor MODELS 6-112 and 6-113	288	3	18	2-speed axle	295	5	
OIL-leak, rear of engine	290	2	4H, 5H, 3R28, 3R38	REAR QUARTER WINDOW MECHANISM	284	7	1953-1954 K
leak, timinggearcover	290	4	1954 Champ. 3R5, 10, 15	REAR SPRING BUSHING REMOVER AND REPLACER J-4655	286	9	Station Wagon
loss of pressure	286	4	4H, 5H (C&K)	REAR WINDOW - defroster; rear speaker	287	5	Regal Land Cruiser
"multi-vis"	290	1		glass	286	4	15G, 5H
OLIVE GREEN METALLIC ENAMEL	294	4		RETURN CLAIMED PARTS	286	6	
ONTARIO BLUE ENAMEL	287	4		RIGHT AND CLEAN PART	284	1	
OVERDRIVE - filling governor, cover	288	5		RuGLYDE	295	4	
	292	2	14G, 15G, 4H, 5H	- S -			
cut-in speeds	284	5	1954 Champ.	SAFFORD CREAM ENAMEL	287	3	
- P -				SAGINAW GREEN ENAMEL	294	3	
PACKAGE COMPARTMENT DOOR PAINT - acid resistant enamel for battery carriers formulas	290	5	15G, 5H	SANDUSKY BEIGE ENAMEL	287	3	
	289			SEAT - back rub	286	1	Coupe & Hardtop
formulas	287	3	1954 Pass. Cars	three more inches in cargo compartment	295	3	1954 Station wagon
formulas	294	4	1955	tubular frame	294	4	E Series
overspray removal	289	1		SELECTOR LINKAGE ADJUSTMENT	289	1	15G, 5H With AD & PS
there's profit in it	291	4		SHERIDAN GREEN ENAMEL	294	4	
PARKING BRAKE HANDLE, CABLE	284	3	4H, 14G, C&K	SHDCK ABSORBERS - heavy-duty	291	1	
PERFECT CIRCLE PISTON RINGS	288	1	All	SHDSTONE RED ENAMEL	287	4	
PHILCO DIRECTORY	286	6		SONORA BEIGE ENAMEL	294	4	
PIMA RED ENAMEL	294	4		SPARE TIRE COVER ANTI-RATTLER	284	2	15GD, 5HD
PISTON RINGS - PERFECT CIRCLE	288	1	All				

REFERENCE	EBU		MDEL	REFERENCE	BL 0.	PAGE	MDEL
	Nb	AGE					
S - Cont'd.							
SPARK PLUG - gasket specifications (J7)	292	3		TRANSMISSION (AUTOMATIC)- Cont'd.			
SPEAKER - rear	285	3		U-joint flange	294	3	AD
	287	5	Regal Land Cruiser 1955	upshift, max. kickdown speeds	295	1	16G8, 9H With AD
SPECIFICATIONS- revision SPEEDOMETER AND REAR AXLE CHARTS	295	4		TRANSMISSION - 5-speed synchromesh	296		
SPICER POWER TAKE-OFF	284	5	1954 Pass. Cars	TRANSMISSION - 4-speed synchromesh assembly (T98)	292	3	3R Series
	288	8	3R16, 17, 28 38 & T98 Synchromesh Trans.	TRANSMISSION (OVERDRIVE)- filling governor, cover	288	5	
SQUEAK - weather seal-to-metal	286	4		speeds	292	2	14G, 15G, 4H, 5H
STEERING - power, Cover gasket	291	4	14G, 15G, 4H, 5H	TRUNK - moisture in lid	284	5	1954 Champ.
STEP PLATES	291	3	2R & 3R	TUBELESS TIRE REPAIRS	286	8	1953- 1954
STEWART-WARNER DIRECTORY	288	5		TUBULAR FRAME SEAT	294	1	
STORAGE, NEW VEHICLES	286	2		!- SPEED AXLE	294	4	E Series
STRIPPED ENGINES - truck	289	5		!- SPEED AXLE CHART	295	5	
STROMBERG CARBURETORS	284	5	1954 Comm		286	10	
- T -							
TAPPET WRENCH	287	7	V8	J-JOINT FLANGE	294	3	AD
THERE'S PROFIT IN PAINT!	291	4		UNDERCOATING	294	1	1955
TILDEN GRAY ENAMEL	294	4		overspray	289	4	
30 AMP FUSE, FOG LIGHT	284	1	15G, 5H	JPHOLSTERY - nylon, waterspots	295	2	
TIMING GEAR COVER-oil leak	290	4	1954 Champ. 3R5, 10, 15	UPSHIFT - max. kickdown speeds	295	1	16G8, 6H With AD
THROTTLE VALVE BLADES, STROMBERG CARBURETORS	291	2	V8				
TIRES - pressures	284	5	1954	-V-			
RuGlyde	295	4		VALVES 0 setting plate	284	3	3H
tubeless repairs	294	1		spring cover	285	1	G-15G
TRANSMISSION - speedometer and rear axle charts	284	5	1954 Pass. cars	tappet adjustment	292	2	V8
				tappet wrench	287	7	V8
gearshift linkage	285	3	14G, 15G, 4H, 5H	VELVET BLACK ENAMEL	287	4	
				VIBRATION DAMPER - engine flywheel	292	3	V8
gearshift linkage adjustment	286	3	14G, 15G, 4H, 5H	VIENNA BLUE ENAMEL (COOK)	287	4	
				VIENNA BLUE ENAMEL (DUPONT)	287	3	
TRANSMISSION (AUTOMATIC)- failure to move forward after reverse operation	290	3		VIENNA BLUE ENAMEL (O'BRIEN)	287	5	
gasket kit	295	1	15G	VISTA GREEN ENAMEL	287	4	
erratic multiple disc clutch in automatic	290	2		- W -			
governor valve springs	295	1	1954-1955 AD	WINDOW - rear glass	286	4	15G, 5H
multiple disc clutch friction discs	292	2	15G	WINDOW GLASS - handle on	294	1	15GD, 5HD
selector linkage adjustment	289	1	15G, 5H With AD & PS	WINDSOR BLUE ENAMEL	294	4	
T - Cont'd.							